







F161






F162C






16341



F164

## ESD RESISTANCE TABLE TM



The conversion into ohms/square per ASTM D-257 is accomplished by taking one decade from the above ohms reading. Example: ten to the three ohms is approximately the same as ten to the four ohms/square.

Figure 5

•